www.technicalindustries.com

## **Technical Industries Job Description**

## **NDT Superintendent**

- To operate the UT and EMI units and to train safely all UT and EMI inspector trainees.
- To maintain all UT and EMI units and make sure they are calibrated, clean, painted, and in good working order at all times. No equipment parts may be taken out without being immediately replaced.
- To keep track of all transducers check each one properly and document each one. Be sure to keep all
  documentation on file.
- Make sure all inspection reports and paper work are filled-out correctly. Make sure strip charts and calibration charts for each pipe are documented.
- Assist in writing and improving S.O.P and Quality Manual.
- Check for safety hazards daily, report any hazards found to the safety supervisor and to your supervisor.
- Hold reasonable safety meeting with your crew.
- Make sure 3<sup>rd</sup> party personnel and outside contractors working in the yard follows the safety rules and the company policy hand book.
- Add more transducers to the UT head.
- Place a maintenance checklist on the wall in each unit.
- Report any problems with the UT or EMI units to your supervisor.
- To perform jobs given to him by his superior safely.

## Qualifications:

- High School Diploma or GED or higher education.
- Must read and write English.
- Must have a minimum of 3 years experience NDT technical and safe operation.
- Must have ASNT certified minimum level 2 in UT, MT, Dye Pentrant, MPI & EMI.
- Must have supervision experience and familiar with Safety, Technical and ISO procedures.
- Must clear back ground check and pass physical examination.
- Must present valid drivers licenses.