Technical Industries Job Description

NDT Supervisor:

- To receive his work orders from his supervisor.
- To supervise the day work of the inspection crews and other inspection work taking place.
- To supervise work outside Technical Industries, Inc. Houston facility.
- To make sure all time is productive.
- To make sure the area that the workers are working in is safe.
- To make sure all employee names written on their safety hats, hard toe shoes, gloves, and glasses and they are wearing safely and following the company policy.
- To make sure all equipment and gauges are maintained, calibrated, and are in working order at all times and that all calibration documents are correct and on file.
- To prevent abuse of equipment and gauges and the waste of material.
- To distribute all necessary equipment and material needed for the inspection jobs. No equipment parts may be taken
 out without being immediately replaced.
- To collect and check the condition of all equipment and gauges and material returned after a hob is completed. Repair as needed.
- To do the RSC (Rotary Shoulder Connection) dimensional readings and the RSC re-facing to drill pipe.
- To make sure all paper work done correctly and turned into the supervisor on time.
- To check for safety hazards and report any found to the safety supervisor or to your supervisor.
- Shall train new inspectors. Supervise the work and make sure everyone is working safely and following the company policy handbook.

Qualifications:

- High School Diploma or GED or higher education.
- Must read and write English.
- Must have a minimum of 5 years experience technical and safety.
- Must have ASNT certified minimum level 2 in UT, MT, Dye Pentrant, MPI & EMI.
- Must have supervision experience and familiar with Safety, Technical and ISO procedures.
- Must clear back ground check and pass physical examination.
- Must present valid drivers licenses.