## **Technical Industries Job Description**

## **OD Imaging Computer Technician**

- To receive his work from his supervisor.
- To maintain and train to operate FLUT and EMI mechanical systems (grease, check drive belts, and rollers and tighten bolts etc.) No equipment parts may be taken out without being immediately replaced.
- To operate the transfer of pipe being inspected by the FLUT or EMI unit.
- To mark all indications found by the FLUT and EMI unit doing the inspection of pipe.
- To apply all Technical Industries, Inc. descriptive stencils and dye stamps.
- To assist on special services i.e. 3D Visonic<sup>™</sup> OD ovality, and dimensions.
- To make sure his work area is safe.
- To follow all safety rules and follow company policy.
- To check for safety hazards daily and report any hazards found to safety supervisor and his supervisor.
- To perform all jobs given to him by his supervisor safely.

## Qualifications:

- High School Diploma or GED or higher education.
- Must read and write English.
- Must have a minimum of 1 years experience technical and safety.
- Could have ASNT certified minimum level 1 in UT, MT, Dye Pentrant, MPI & EMI.
- Must have supervision experience and familiar with Safety, Technical and ISO procedures.
- Must clear back ground check and pass physical examination.
- Must present valid drivers licenses.